FIG. 1





FIG. 2






FIG. 3




FIG. 4




FIG. 5




FIG. 6






FIG. 7A








FIG. 8 250 CUBIC CRYSTAL PHASE 200 Tc TEMPERATURE (°C) 150 TETRAGONAL CRYSTAL PHASE 100 Trt 50 PSEUDOCUBIC CRYSTAL PHASE 0 -50 ^L 0.1 0.3 0.2 0.4 0.5 PMN Χ PT -

(MOLE FRACTION)

FIG. 9




FIG. 10

